



JON M. HUNTSMAN, JR.  
Governor  
GARY R. HERBERT  
Lieutenant Governor

**State of Utah**  
**DEPARTMENT OF NATURAL RESOURCES**  
**Division of Oil, Gas & Mining**

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

**Inspection Report**  
**Minerals Regulatory Program**  
May 21, 2008

Reviewer PTB

<b>Mine Name:</b> TME Asphalt Ridge	<b>Permit Number:</b> M0470089
<b>Operator Name:</b> TME Asphalt Ridge LLC	<b>Inspection Date:</b> 05-21-08
<b>Inspector(s):</b> L Heppler	<b>Time:</b> 4:00 pm
<b>Other Participants:</b> Tony Hite, Jody Atwood	<b>Mine Status:</b> Act

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Bond Renewal Date:** 04-11-2009 **Bond Amount:** \$18,600 This mine is converting to a LMO (M0470089)

**Purpose of Inspection:** This was a routine annual inspection.

**Inspection Summary:** Environmental fence as been installed next to drainage. No trash or safety hazards noted. Main access road has been paved. No topsoil has been stockpiled at this time.

**Conclusions and Recommendations:** Continue to monitor this site when in the area.

Photos were taken to document site conditions.

**Inspector's Signature**

LAH:pb

cc: TME Asphalt Ridge LLC

FEE

P:\GROUPS\MINERALS\WP\M047-Uintah\M0470089-TMEAsphaltRidge\draft\Insp\_TMEAsphaltRidge\_05-21-08.doc

Photos Taken 05-21-08

